

From: [education@scwmetalclub.com](mailto:education@scwmetalclub.com)  
Sent: Saturday, May 2, 2020 7:10 PM  
Subject: Email #6: Setting up Toolpaths & Tips for Cleaning Metal Art Files  
Attachments: Toolpathing - Larry V4-Rev3.pdf

<https://www.scwmetalclub.com/tooltips/vcarve-pro-toolpathing.pdf>

**\*\*\*Please Note: An On-Line Survey was Sent Out to the VCarve PRO Email Distribution List (About 63 Club Members) in April to find out how the Information was being Received by Club Members. This Survey Concluded on April 27<sup>th</sup> and the Results are Shared in an Upcoming Email #7. \*\*\***

Hello, All. Please see the attached document which gives you an update on the following topics:

- VCarve Preliminary Survey Results:
  - Please complete the survey emailed to you on April 13<sup>th</sup> if you have not already done so.
  - Deadline is Monday, April 27<sup>th</sup> at 8:00am...thank you!
- Directions for Setting up VCarve Pro 2D Profile Toolpaths:
  - Step by Step Instructions & Screen Shots to walk you through this process.
- YouTube video tutorial of new and excellent tips for cleaning up metal art patterns.

We are pleased to know that several members have taken learning VCarve Pro very seriously and are moving ahead quickly. Keep up the great learning!

However, if you no longer wish to receive these VCarve emails, please reply to this email and we will remove you from the list.

Thank you for your

support, Your

VCarvePro Team  
SCW Metal Club